


Heli-Max™

AXE™ 400



Axe 400 CNC Upgrade Parts Exploded View and Parts List



- 1** 2x10mm Phillips Machine Screw
- 2** 2x5x2mm Ball Bearing
- 3** 2x3.4x0.68mm Shim
- 4** CNC Mixer Arm
- 5** Linkage Ball
- 6** 2x2.8x0.25mm Shim
- 7** Linkage Ball Screw
- 8** CNC Head Block
- 9** CNC Head Button
- 10** Head Button Mounting Screw
- 11** 3x8x3mm Ball Bearing
- 12** Bearing PreLoad Spacer
- 13** 3mm Nylon Insert Lock Nut
- 14** CNC Main Blade Grip
- 15** 3x15mm Socket Head Cap Screw
- 16** 2x5x2.5mm Flanged Ball Bearing
- 17** 2mm Step Seesaw Mounting Screw
- 18** CNC Seesaw
- 19** 2x5mm Phillips Machine Screw
- 20** 2x3mm Set Screw
- 21** CNC Flybar Carrier Arm

Heli-Max Axe™ 400 CNC Upgrade Parts		
Part #	Description	Contains
HMXE7493	CNC Mixer Arms	1 3 4 6 x2 2 5 7 x4
HMXE7483	CNC Head Block	8 x1
HMXE7482	CNC Main Blade Grips	11 x4 5 7 12 13 14 15 x2
HMXE7487	CNC Seesaw	18 x1 2 16 17 x2
HMXE7484	CNC Flybar Carrier	19 x4 20 21 x2
HMXE7497	CNC Head Button	9 10 x1

