

T14MZ/FX-40 SOFTWARE UPDATE CHANGES (Editor Version:1.7, Encoder Version:1.47)

This software update adds or changes the following functions. In addition to the manual originally supplied with your system, please now refer to the following new instructions:

The GYRO2/GYRO3 function can now be set with a helicopter. (Helicopter)

* When using the gyro2/gyro3 function, assign gyro2/gyro3 to any channel on the function screen.

* Function name setting is reflected in the title of the gyro details setting screen.

1) When Gyro setting menu is chosen, the rate setting screen of each gyro is displayed.


* A rate and the AVCS mode setting of each gyro are possible with this screen.

* The active rate is shown in a green background on the display.


Servo test

Servo test cannot now turn on in the next state, because it is dangerous for the throttle to suddenly become engaged.

- Throttle cut is on. [Airplane/Helicopter]
- Throttle hold is on. [Helicopter]
- Condition hold is on. [Helicopter]



2) When a gyro function button is chosen, the detailed setting screen of each gyro is displayed.



↓ (Open detail menu)

