

T4PX Software Update Changes (Version 1.2)

This software update modifies features found on the T4PX. If you have questions about these updated directions, please consult your instruction manual or futaba-rc.com for further details. Refer to the original manual where applicable but replace the steps indicated below with these instructions.

-
- 1.** Dual rate setting affects not only a steering channel but also a steering 2 channel.

 - 2.** Position of the throttle trigger to start a timer is changed to 50%.

 - 3.** The grip vibrator is activated at not only an alarm time but also a navi alarm time.

 - 4.** Repeating trim operation is temporally stopped when a value assigned the trim reach zero position.
-