

CGY750 Software Update Function (VERSION 1.31)

■ This firmware update resolves two minor bugs present in V1.30 CGY-750 firmware.

1. GY-701/CGY-750 GY Link data copy tool bug: “Write Error” may occur when parameters saved to a PC are transferred to a CGY-750.

>> V1.31 corrects this bug. A saved model file will correctly upload to the CGY-750.

2. When attempting to store rudder trim into the CGY-750’s memory, the rudder trim may not be saved.

>> V1.31 corrects this bug and allows correct rudder trim memorization.

■ **General Notes :** V1.31 firmware has the exact same functions and performance as V1.30 firmware; no changes were made. All previous instructions for V1.30 firmware still apply. Firmware updating instructions previously used for V1.30 firmware apply to V1.31 as well.

■ **Notes :** When updating to V1.31 firmware from any version PRIOR to V1.30 (e.g. V1.0-V1.2), the **INIT DATA** screen appears with the first power up after update and must be allowed to disappear before proceeding; never power down the CGY-750 before the **INIT DATA** screen disappears. Conversely, when updating from V1.30 to V1.31 firmware, the **INIT DATA** screen does NOT appear with first power up. The display will simply show Ver:1.31.